

Installation Instructions Atlas Cleat

- 1) Position the cable clamp and fixing (not supplied) onto the support structure.
- **Multi Cable**



Single Cable









WARNING - to prevent eddy currents and heating of the cleat the top tensioning bolt is made of stainless steel. Ensure that only this bolt is used and that bridging cannot take place.

Inst 30 - Atlas Cleat Issue 05 23/08/11

> **Ellis Patents Ltd** High Street, Rillington, Malton, North Yorkshire YO17 8LA United Kingdom

+44 (0)1944 758395 +44 (0)1944 758808 sales@ellispatents.co.uk www.ellispatents.co.uk

2) Install the cable.

- 3) Locate the other half of the cable clamp. Secure with a nut
- 4) Important: Do not over tighten the cleat. The cleat should secure the cable but does not need to be so tight that the cable bulges at either side of the cleat.
- and washer (not supplied) to the support structure and tighten.

